

INSPECTION REPORT

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

Inspection Date & Time: <u>2/29/2000 / 10:00A.M.-2:00P.M.</u>

Partial: xxx Complete: Exploration:

801-359-3940 (Fax) Lowell P. Braxton 801-538-7223 (TDD) Division Director

Date of Last Inspection: 1/25/2000

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025							
Permittee and/or Operator's Name: Co-Op Mining Company							
Business Address: P. O. Box 1245, Huntington, Utah 84528							
Type of Mining Activity: Underground XXX Surface Prep. Plant Other							
Company Official(s): Charles Reynolds							
State Officials(s): Steve Demczak Federal Official(s): None							
Weather Conditions: 30', Snow Covered, 6-12"							
Existing Acreage: Permitted-1032.75 Disturbed-24 Regraded-0 Seeded-0 Bonded-24							
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded							
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/_ Bond Forfeiture							
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Michael O. Leavitt

Governor

Substantiate the elements on this inspection by checking the appropriate performance standard.

For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.

For <u>partial inspections</u> check only the elements evaluated.

- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	NI/A	COMMENTS	NOW/END
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	EVALUATED [_]	<u>N/A</u> L1	COMMENTS []	NOV/ENF
2.	SIGNS AND MARKERS	[XX]		[XX]	늄
3.	TOPSOIL	[XX]	H		븁
4.	HYDROLOGIC BALANCE:	172771		1232.21	
a.	DIVERSIONS	[XX]	[]	[XX]	f 1
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX] [XX]	겁	[XX] [XX]	<u> </u>
c.	OTHER SEDIMENT CONTROL MEASURES	[]	- 11	[]	급
d.	WATER MONITORING	[]	Ħ	Ħ	台
e.	EFFLUENT LIMITATIONS	Ħ	Ħ	Ħ	Ħ
5.	EXPLOSIVES	[XX]	Ti.	[XX]	Ħ
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	Ħ	[]	Π
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	Π	[XX]	Fi
8.	NONCOAL WASTE	XX	Π	XX	Ti.
9.	PROTECTION OF FISH, WILDLIFE AND	<u>, , , , , , , , , , , , , , , ,</u>			
	RELATED ENVIRONMENTAL VALUES	[]	[]	[]	
10.	SLIDES AND OTHER DAMAGE	i i	Π		. 🗔
11.	CONTEMPORANEOUS RECLAMATION	i i	Π	<u>[]</u>	口
12.	BACKFILLING AND GRADING	ĪĪ	口		\Box
13.	REVEGETATION	īī	$\overline{\square}$		$\overline{\Box}$
14.	SUBSIDENCE CONTROL		\Box	\Box	\Box
15.	CESSATION OF OPERATIONS	<u> </u>	\Box	$\overline{\Box}$	$\overline{\square}$
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	\Box	П	Ш
b.	DRAINAGE CONTROLS		$\overline{\square}$	$\overline{\square}$	
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box	$\overline{\Box}$	\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS		П	\Box	\Box
19.	AVS CHECK (4th Quarter-April, May, June)(date)		\Box	\Box	\Box
20.	AIR QUALITY PERMIT	口	$\overline{\square}$	\Box	$\overline{\Box}$
21.	BONDING & INSURANCE	īī	<u>[]</u>	[]	[]

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 2/29/2000

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS -

Identification signs meet the requirements of the R645 Coal Rules. The perimeter markers were spot-checked and are located around the perimeter of the disturbed areas. Topsoil ID signs are located on the topsoil piles as required in the R645 Coal Rules. There are stream buffer zone signs posted throughout the mine property.

3. TOPSOIL -

The topsoil piles were inspected with no signs of wind or water erosion. These piles were covered by snow.

4A. DIVERSIONS -

The diversions were checked and functioning. Maintenance will need to be performed when the area dries out.

4B. SEDIMENT PONDS -

There were no hazardous conditions noticed. No ponds were discharging.

5. EXPLOSIVES -

There are explosives boxes on the property which are located on the upper end of the disturbed area.

7. REFUSE PILE -

There was not a refuse pile on site.

8. NON-COAL WASTE -

The area was clear of non-coal waste material.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Charles Reynolds (Co-Op)

Henry Austin (OSM)

Given to Proceedings (Co-Op)

Given to: <u>Pam Grubaugh-Littig (DOGM)</u> Filed to: <u>Price Field Office</u>

Date: March 1, 2000

Inspector's Signature: #3

Stephøn J. Demczak